



U.S. Department of Labor

Occupational Safety & Health Administration

www.osha.gov

Search

[GO Advanced Search](#) | [A-Z Index](#)

Accident Search Detail

Accident 201162070 - Tip Over of A Gradeall Forklift

Accident 201162070 -- Report ID: 0950641 -- Event Date: 07/25/2000

Inspection: 126060573 Open: 07/25/2000 SIC: 1751 Ayala Construction Inc.

OSHA 36# 362572901 Ee#1 Worked as a carpenter for Ayala Construction, 20116 Hinsdale Ave., Torrance Ca (SIC Code-1751), 310-938-2797. At the time of subject accident he was driving a Gradeall brand, rough terrain forklift, Ser #144702, Model# 534b, with 8000 lb capacity. He was attempting to place a load of plywood on the floor of a wood framed condominium. The load was not straight with the front of the structure so he backed up tried to reposition it. As he did he had the steering wheel turned in soft sandy soil, and the machine tipped on it. Because he was wearing a seat belt his injuries were limited to **four fingers** on his Left hand, 2 broken and 2 requiring sutures, from hanging on to the roll bar as it tipped.

End Use	Proj Type	Proj Cost	Stories NonBldgHt Fatality
Multi-family dwelling	New project or new addition	\$50,000 to \$250,000	2

Inspection	Age	Sex	Degree	Nature	Occupation	Construction
1 126060573	38	M	Non Hospitalized	Fracture	Carpenters	FallDist: 05 Cause: Site grading and rock rem FatCause: Exterior cladding

[Back to Top](#)
www.osha.gov
[www](#)

[Contact Us](#) | [Freedom of Information Act](#) | [Information Quality](#) | [Customer Survey](#)
[Privacy and Security Statement](#) | [Disclaimers](#)

Occupational Safety & Health Administration
 200 Constitution Avenue, NW
 Washington, DC 20210